

### OMRON

# Product Discontinuation Notices

September 1, 2010

**Cam Positioners** 

No. 2010249E

## Discontinuation Notice of USB cable for Cam positioner H8PS. Y92S-40

#### **Product Discontinuation**

#### **Recommended Replacement**

No recommended replacement in OMRON



Y92S-40



U2C-MF20BK (ELECOM CO.LTD)

Discontinuation date: The end of June, 2010

#### Caution on recommended replacement

There are no recommended products in OMRON.

Recommended replacement is U2C-MF20BK ELECOM CO.LTD.


If you can't purchase recommended replacement, please purchase commercially available USB cable that attached ferrite core.

#### Difference from discontinued product

Model	Body Color	Dimen sions	Wire connection	Mounting Dimensions	Charact eristics	Operation ratings	Operation methods
U2C-MF20BK (ELECOM)	-	**	**	-	**	**	**

- \*\* : Fully compatible
- \* : The change is a little/Almost compatible
- -- : Not compatible
- : No corresponding specification

#### **Body color**



#### **Function**

