

OMRON

Product Discontinuation Notices

January 5, 2011

Photoelectric Sensors

No. 2011010E

Discontinuation Notice of Beam checker Type E39-VX

Product Discontinuation Beam checker

Recommended Replacement

Handy checker

X

E39-VX

E39-VA

Discontinuation date: The end of January, 2012

Caution on recommended replacement

E39-VA can be used as a power supply for a photoelectric sensor as well as E39-VX.

E39-VA is able not to connect them though E39-VX can connect the E32 fiber unit and the E3C amplifier separation sensor head. Therefore, an optical axis is matched and there are neither a function nor an analog output terminal.

Difference from discontinued product

Model	Body Color	Dimen sions	Wire connection	Mounting Dimensions	Operation ratings	Operation methods
E39-VA	*	*	*	*	 	*

- ** : Fully compatible
- * : The change is a little/Almost compatible
- -- : Not compatible
- : No corresponding specification


Product Discontinuation and recommended replacement

Product	discontinuation	Recommended replacement		
Model	Product code	Model	Product code	
E39-VX	E39V1001M	E39-VA	E39V1002R	

Body color

Product discontinuation	Recommendable replacement		
E39-VX	E39-VA		
Light gray	Light gray		

Dimensions



Characteristic

Item	Product discontinuation E39-VX	Recommendable replacement E39-VA		
Power supply voltage	18V (9V two dry batteries)			
Connected sensor	Sensor of current consumption 50mA or less E32 Fiber sensor E3C amplifier separation sensor head	Sensor of current consumption 50mA or less		
Ambient temperature	Operating: 0 to +40°C, Storage: -10 to +55°C			
Battery low detection function	The function is possessed			